

# General Environmental Incident Summary

**Incident:** 4162      **Date/Time Notice:** 7/8/2016      **DEM Incident No:**  
**Responsible Party:** WPX Energy  
**Date Incident:** 6/30/2016      **Time Incident:** 11:40      **Duration:** 2 minutes  
**County:** Dunn      **Twp:** 149      **Rng:** 93      **Sec:** 1      **Qtr:**  
**Lat:** 47.74758      **Long:** -102.51720      **Method:** Navigation quality GPS  
**Location Description:** From Mandaree, continue west on BIA 12 until you intersect with BIA 10. Turn left onto BIA 10 and follow until you are almost to the end of BIA 10. The well pad, Buffalo 1-36H, will be labeled on the left hand side.  
**Submitted By:** Robert Raup      **Affiliation:** EHS Supervisor  
**Address:** 10471 One A St. SW  
**City:** Killdeer      **State:** ND      **Zip:** 58640

## Received By:

**Contact Person:** Robert Raup  
10471 One A St. SW  
Killdeer, ND 58640

**Distance Nearest Occupied Building:**      **Release Contained:** Yes

**Type of Incident:** Compressor Lube Oil

**Description of Released Contaminant:** Hydraulic Oil

**Volume Spilled:** 5.00 gallons      **Ag Related:** No

**EPA Extremely Hazardous Substance:** Unknown      **Reported to NRC:** Unknown

## Cause of Incident:

The sight glass on the compressor discharge scrubber broke which caused a small amount of hydraulic oil to be discharged to the well pad surface.

## Risk Evaluation:

There were no immediate risks involved. The medium affected above was the gravel on the surface of the well pad.

**# of Fatalities:**      **# of Injuries:**      **Affected Medium:** 09 - other

## Potential Environmental Impacts:

There were no potential for environmental impacts as the hydraulic fluid remained on the well pad and remained in the gravel.

## Action Taken or Planned:

The release was contained to the well pad surface. A cleanup crew arrived onsite and scraped up the impacted gravel, near the compressor, that was affected.

**Wastes Disposal Location:** A special waste landfill. The size of the release does not meet any specific notification requirements; however, the landfills require non E&P exempt materials to be reported and sampled prior to acceptance.

## Agencies Involved:

## ***Updates***

---

***Date:*** 7/8/2016      ***Status:*** Reviewed - Assigned to Other Agency

***Author:*** Suess, Bill

***Updated Volume:***

***Notes:***

MHA Nation has jurisdiction.